





record-USA
4324 Phil Hargett Ct.
Monroe, NC 28110
(704) 289 - 9212


TOP BREAKOUT & BOTTOM GUIDE ASSEMBLIES HM &/OR WOOD DOOR BY OTHERS

MAR2017




**4-56-0001 - LH
BOTTOM GUIDE ASSY.
WOOD DBO**

**4-56-0002 - RH
BOTTOM GUIDE ASSY.
WOOD DBO**



**4-11-0470 LH
Sway Guide Assembly**



**4-11-0471 RH
Sway Guide Assembly**

PART NO.	DESCRIPTION
5-51-4006 CL/DB	Top Catch Extrusion (length req'd)
4-51-1049	Endcap, Top Catch
4-51-1038/1039	Door Catch Housing & Interlock
4-52-0012	Ball Catch Assembly
4-52-1004	SX Lower Interlock
4-52-0001	SX Upper Pivot Assembly
	4-51-1051 Upper Pivot Arm
	4-51-1052 Lower Pivot Arm
	4-51-1053 Pivot Pin
	9-07-0027 Bushing
	9-99-4626 Snap Ring
81-0011-2815	Bolt, 5/16-24 X 1" FHSCS
81-0016-2771	Bolt, 3/8-24 X 1" SCS
Include Mounting Hardware	