




Replacement Parts

Record HA8-SP



Item	Category	Part #	Description
1	Operators	W7-105L	LH 1/8 hp operator
		W7-105R	RH 1/8 hp operator
		W7-106L	LH 1/8 hp, push & go operator
		W7-106R	RH 1/8 hp, push & go operator
2	Header Cap	W5-557	Header Plastic Cap
3	Control Board	W7-130-1	HA Digital Control Board
4	Fuses	W5-422	3amp fuse (HA8)
		W5-430	4amp fush (FA8)
5	Push Arm	W7-200	complete push arm-clear
		W7-205	complete push arm-bronze
		W5-502C	cast portion only- clear
		W5-502B	cast portion only-bronze
6	Z Arm (Pull)	W5-506C	Z Arm-RH-Clear
		W5-505C	Z Arm-LH-Clear
		W5-506B	Z Arm-RH-Bronze
		W5-505B	Z Arm-LH-Bronze
		W5-508C	Ext Z Arm-RH-Clear
		W5-508B	Ext Z Arm-RH-Black
		W5-507C	Ext Z Arm-LH-Clear
		W5-507B	Ext Z Arm-LH-Black
5	Arms	W5-506C	Z Arm-RH-Clear
		W5-505C	Z Arm-LH-Clear
		W5-506B	Z Arm-RH-Bronze
		W5-505B	Z Arm-LH-Bronze
		W5-508C	Extended Z Arm-RH-Clear
		W5-507C	Extended Z Arm-LH-Clear
		W5-508B	Extended Z Arm-RH-Black
		W5-507B	Extended Z Arm-LH-Black

Item	Category	Part #	Description
7a	Pull Arm Track - short (for z arm)	W5-550	Pull track assembly - clear
		W5-555	Pull track assembly - bronze
7b	Pull Arm Track - long (for Universal/Center Spindle)	W5-551	Pull track assembly long-clear (for Univ/Center Spindle)
		W5-556	Pull track assembly long-bronze (for Univ/Center Spindle)
8	Universal Arm	W5-512C	Universal Arm-clear
		W5-512B	Universal Arm-bronze
11	AUX Power Supply Kit (optional)	WL-PWRKIT	RS-25-24 Power supply kit
12	Rocker Switch	WL-ROCKER-SWITCH	On/off/hold open 3 position switch
13	Magnet Sets	W5-416	magnet set, detects back check and latch check phases
14	Reed Switch	W5-415	reed switch & harness; communicates to control board the position of door
15	Harness Cable	W5-415-2	Communicates to control board the position of door